## Extended Five-Year or Three Thousand (3000)-Hour Stationary Standby Limited Warranty

This Kohler Standby Generator System has been manufactured and inspected with care by experienced craftsmen. If you are the original purchaser, Kohler Co. warrants for five years or three thousand (3000) hours, whichever occurs first, that the system will be free from defects in material and workmanship if properly installed, maintained, and operated in accordance with Kohler Co.'s instruction manuals. A Kohler distributor, dealer, or authorized representative must perform startup.

This warranty is not effective unless a proper extended warranty registration form and warranty fee have been sent to Kohler Co. within one year of supervised startup.

During the warranty period, repair or replacement at Kohler Co.'s option will be furnished free of charge for parts, provided an inspection to Kohler Co.'s satisfaction discloses a defect in material and workmanship, and provided that the part or parts are returned to Kohler Co. or an authorized service station, if requested. This extended warranty expires five full years after date of startup or after 3000 hours of operation, whichever occurs first. Labor is chargeable to warranty for the first two years of the five-year warranty.\*

This warranty does not apply to malfunctions caused by damage, unreasonable use, misuse, or normal wear and tear while in your possession.

\*Some restrictions may apply. Contact your Kohler distributor/dealer for full details.

The following will not be covered by this warranty:

- 1. Normal engine wear, routine tuneups, tuneup parts, adjustments, and periodic service.
- Damage caused by accidents, improper installation or handling, faulty repairs not performed by an authorized service representative, or improper storage.
- 3. Damage caused by operation with improper fuel or at speeds, loads, conditions, modifications, or installation contrary to published specifications or recommendations.
- 4. Damage caused by negligent maintenance such as:
  - a. Failure to provide the specified type and sufficient lubricating oil.
  - b. Failure to keep the air intake and cooling fin areas clean.
  - c. Failure to service the air cleaner.
  - d. Failure to provide sufficient coolant and/or cooling air.
    e. Failure to perform scheduled maintenance as prescribed in supplied manuals.
  - f. Failure to exercise with load regularly.
- 5. Original installation charges and startup costs.
- 6. Starting batteries and the following related expenses: a. Labor charges related to battery service.
  - b. Travel expense related to battery service.
- 7. Engine coolant heaters, heater controls, and circulating pumps after the first year.

- 8. Rental of equipment during performance of warranty repairs.
- 9. Non-Kohler-authorized repair shop labor without prior approval from Kohler Co. Warranty Department.
- 10. Engine fluids such as fuel, oil, or coolant/antifreeze.
- 11. Parts purchased from sources other than Kohler. Replacement of a failed Kohler part with a non-Kohler part voids warranty on that part.
- 12. Radiators replaced rather than repaired.
- 13. Fuel injection pumps not repaired locally by an authorized servicing dealer.
- 14. Shop supplies such as adhesives, cleaning solvents, and rags.
- 15. Expenses incurred investigating performance complaints unless the problem is caused by defective Kohler materials or workmanship.
- 16. Maintenance items such as fuses, filters, spark plugs, loose/leaking clamps, and adjustments.
- 17. Labor and travel charges for third, fourth, and fifth years of warranty.

A Startup Notification form must be on file at Kohler Co. A Startup Notification form must be completed by Seller and received at Kohler Co. within 60 days after the date of initial startup. Standby systems not registered within 60 days of startup will automatically be registered by Kohler Co. using the Kohler Co. ship date as the startup date.

To obtain warranty service, call 1-800-544-2444 for your nearest authorized Kohler service representative, or write Kohler Co., Generator Service Department, Kohler, WI 53044 USA.

KOHLER CO. SHALL NOT BE LIABLE FOR SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES OF ANY KIND including, but not limited to, incidental consequential labor costs, installation charges, telephone charges, or transportation charges in connection with the replacement or repair of defective parts.

This is our exclusive written warranty. We make no other express warranty, nor is anyone authorized to make any in our behalf. ANY IMPLIED OR STATUTORY WARRANTY, INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS OF PURCHASE, is expressly limited to the duration of this warranty.

Some states do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you.

This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.



KOHLER CO. Kohler, Wisconsin 53044 Phone 920-565-3381, Fax 920-459-1646 For the nearest sales/service outlet in the US and Canada, phone 1-800-544-2444 KohlerPowerSystems.com

TP-5498 12/99c